HONDA Service Bulletin

Model	Applicable To	File Under	Bulletin No.
1994	See VEHICLES	BRAKES	94-029
ACCORD	AFFECTED		Issue Date
			NOV 4. 1996

Brake Fluid Leak

(Supersedes 94-029, dated October 3, 1994)

SYMPTOM

The brake fluid level is low in the ABS reservoir, and fluid appears to be leaking from under the label on the ABS accumulator.

PROBABLE CAUSE

The ABS accumulator internal O-ring is damaged, allowing brake fluid to leak out. (Refer to service bulletin 96-050, *Brake Fluid Leak From the ABS Modulator*, for seepage from the plugs.)

VEHICLES AFFECTED

Sedan:

Japan prod. Ohio prod.	- thru VIN JHMCD5 RC049854 - thru VIN 1HGCD5 RA115174
Coupe	- thru VIN 1HGCD7 RA038384
Wagon	- thru VIN 1HGCE1 RA005648

DIAGNOSIS

Remove the label from the ABS accumulator.

- If the hole behind the label is wet with brake fluid, continue to CORRECTIVE ACTION.
- If the hole is not wet, clean the accumulator and use powder to locate the leak.


CORRECTIVE ACTION

Replace the accumulator and O-ring with the kit listed under PARTS INFORMATION.

- 1. Attach a hose to the bleeder screw and relieve the system pressure. Refer to service manual page 19-128 for the proper procedure.
- 2. Disconnect the 14P and 2P connectors from the modulator.
- 3. Remove the six brake lines from the modulator.
- 4. Remove the wire harness clip from the modulator bracket.
- 5. Remove the three modulator mounting nuts. Remove the modulator from the car.

6. Remove the two mounting bolts and remove the accumulator from the modulator.

NOTE: Do not place the modulator in a bench vise. You could damage the fittings.



- 7. Do not release the nitrogen from the accumulator at this time. The accumulator should be stored, fully pressurized, for 30 days for warranty parts call-in. If it is not called in within 30 days, the accumulator should then be depressurized and discarded.
- 8. Install the O-ring on the new accumulator (see PARTS INFORMATION).
- 9. Install the accumulator on the modulator. Tighten the mounting bolts to 9.8 N·m (1.0 kg-m, 7 lb-ft).
- 10. Install the modulator in the car. Tighten the mounting nuts to 22 N·m (2.2 kg-m, 16 lb-ft).
- Reconnect the brake lines, wire harness clip, and electrical connectors. Tighten the brake lines to 19 N⋅m (1.9 kg-m, 14 lb-ft).
- 12. Fill the modulator and brake reservoirs with Honda brake fluid.

© 1996 American Honda Motor Co., Inc. – All Rights Reserved


ATB 16726-18403 (9611)

CUSTOMER INFORMATION: The information in this bulletin is intended for use *only* by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

- 13. Bleed the brake system. Refer to service manual page 19-6.
- 14. Bleed the ABS modulator. Refer to service manual page 19-129.

Modulator Final Bleeding Procedure

- 15. Connect a piece of 3/8 inch O.D. hose to the pressure side of a hand-held vacuum pump.
- 16. Remove the filler cap from the modulator reservoir. Leave the plastic insert in the modulator opening.
- 17. Start the engine. Hold the vacuum pump hose against the modulator opening insert. To pressurize the reservoir, pump the vacuum pump until you feel resistance (1 to 3 strokes).



- 18. While keeping the reservoir pressurized, have an assistant turn off the engine and then slowly open the modulator bleeder.
- 19. Close the bleeder when brake fluid stops running into the tube.
- 20. Repeat steps 18 through 20 five times to purge the air from the modulator.
- 21. Clear any codes in the ABS control unit memory by removing the ABS B2 fuse in the under-hood ABS fuse box for three seconds.

PARTS INFORMATION

ABS accumulator kit: P/N 57018-ST5-000, H/C 4611174

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation number:	413144	
Flat rate time:	0.8 hour	
Failed part:	P/N 57110-ST7-003 H/C 4251609	
Defect code:	060	
Contention code:	B06	
Template ID:	94-029A NEW	

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.