

1996 Honda Accord Wagon  
F22B2 Engine

Right Side  
(passenger)  
Drive shaft

Should this be  
flush or is a small  
gap acceptable



Manual  
Transmission  
Housing