

There are two (2) alignment marks for the front balancer shaft to make sure that the shaft is positioned correctly.

Location of primary "mark" on the front balancer shaft pulley at the 9 o'clock position.

Front balancer shaft secondary "mark". Note that it is slightly offset and does not align exactly

Location of oil pump alignment mark for the front balancer shaft.

1996 Honda Accord F22B2 Engine

